

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY DATAMASTER MAINTENANCE REPORT

RECEIVED DOSS BANK SHOULD BE CAROL Day at 12:20 pm, May 09, 2010

Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file. DATE OF INSPECTION 204/06 3-1-10 LOCATION OF INSTRUMENT (STREET AND CITY) TIME OF INSPECTION NUNZOG CITY PULICE REPREMENT, BU NUZTH MALN STREET, MUNIOF CITY MU 63456 0851 CHECKLIST: Place a check (-/) to the left of each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unchecked items must be corrected before using instrument. DIAGNOSTIC CHECK (PRINTOUT ATTACHED) COMPUTER **DETECTOR** PROGRAM ☑ FILTERS HEATERS SAMPLE CHAMBER 50 QUARTZ STANDARD ☑ FLOW DETECTOR ☑ CALIBRATION PRINTER D PUMP HIGH SPEED INDICATOR LIGHTS ☑ TIME AND DATE SIMULATOR TEMPERATURE (34 °C ± 0.2°C) ☑ CALIBRATION CHECK -Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP) ☑ 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE O.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) TEST 1 TEST 2 🕶 ./00 TEST 3 📂 _/00 . 099 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) M NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS (DO NOT INCLUDE SIMULATOR TESTS) FOLLOWS: (,10-,14) REFUSALS (0-.04)(.05-.09)(.15 - .19)(Over .19) List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary) INCOMPLETE SAMPLE I.NSTRUMENT MEETS DEPT. OF HEALTH SPECS, PERO MARKETUNG INC., , 10 SOLVETON LOTNO. 0900Z, EXP. 08-31-11 **INSPECTING OFFICER** SIGNATURE PRINT NAME TYPE II PERMIT NUMBER/EXPIRATION DATE TELEPHONE NUMBER *20*033 MO 580-1468 (9-94) AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 09002

EXPIRATION DATE: August 31, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>09002</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain <u>.1206</u> gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is September 1, 2009.

The expiration date for this lot number is August 31, 2011 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc.

State of Missouri DEPARTMENT OF HEALTH



MO 560-0771 (7-88)

PERMIT TYPE II



Lab. 4 (R7-88)

BRANDON C GRIFFIN

DATAMASTER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

and the same when the same of the same Face This Side Down – This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL . BAC DATAMASTER SERIAL NUMBER 204106 63/91/19

STESTING OFFICER: GRIFFIH/8/C OFFICER I.B.: 6429 PERMIT HUMBER: 200033 EXPIRATION DATE: 02-05-2012 MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLANK TEST	. 609	99:97
INTERNAL STANDERD	VERIFIED	89:87
EXTERNAL STAIDARD	. 899	89198
BLANK TEST	. 188	99:08
EXTERNAL STANDARD	. 165	
BLANK TEST	.968	M9:09
EXTERMAL STANDARD	. 166	09:10
DLAHK TEST	. 699	99110

M = 3SIM. = .1 AVG. = ,8996 Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204106 83/01/10 99:51

--- DIAGNOSTIC CHECK ---

COMPUTERS

ÜKHY

PROGRAM (84-87-2889):

HEATERS

SAMPLE CHAMBER:

Sec

FLOW DETECTOR:

ÜKAY

PUMP

HIGH SPEED:

OKAY

DETECTOR:

DKAY

FILTERS

OKAY

QUARTZ STANDARD:

ÜKAY

CHLIBRATIONS

OKAY

PRINTER TEST !"#\$%&^()#+,-,/0123456789:;(=)?@ABCUEF6 HIJKLMHOPORSTUWWXYZ[\]^_'abcdefghijklmno

pgrstuwxyz(1)+"

Operator Signature_

2208-02

gen yn trend i felig in de gegen fan de legen en retrette treitigen fan sterken beskelt fan felig treit

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL HUMBER 204106 03/01/10

ARREST TIME: 08:00

SUBJECT NAME:

TEST

DOB: 01/01/70 SEX: M

STATE/D.L.: MO/1234567890

ARRESTING OFFICER:

GRIFFIN/B/C

OFFICER I.D.: 0429

TESTING OFFICER:

GRIFFIN/B/C

OFFICER I.D.: 0429

PERMIT NUMBER: 20033 BC.G

EXPIRATION DATE: 02-05-20/2

MISCELLANEOUS DATA:

R.F.I. TEST

--- BREATH ANGLYSIS ---

ØLAMK TEST INTERMAL STAMDARD RADIO INTERFERENCE

.000 VERIFIED

99:14

VERIT1

gy: 14

Operator Signature

2208-02